



34°57'W

34°57'W

34°57'W

34°57'W

LANDSLIDES SCARS IN RECIFE/PE - BRAZIL

-  Landslides Scars
-  Municipal Boundary



Pre-disaster image: Google Satellites
Post-disaster image:
HIRI/Pleiades 1B - 01.06.2022
© CNES (2022), Distribution Airbus DS.



GEOGRAPHIC COORDINATE SYSTEM
DATUM: WGS 84

S 8° 8'

S 8° 8'

S 8° 8'

S 8° 8'

S 8° 8'

S 8° 8'

S 8° 8'

S 8° 8'

34°57'W

34°57'W

34°57'W

34°57'W

0 100 200 m

