

34°58'W

34°58'W



LANDSLIDES SCARS IN RECIFE/PE - BRAZIL

 Landslides Scars



Post-disaster image:
HIRI/Pleiades 1B - 01.06.2022
© CNES (2022), Distribution Airbus DS.



GEOGRAPHIC COORDINATE SYSTEM
DATUM: WGS 84

34°58'W
34°58'W34°58'W
34°58'W

34°58'W

34°58'W