


FLOOD IN HAITI Momance River

Act-995 Call-1142



Google Terrain

The pre-disaster and post-disaster images show that no structures were affected. The Momance River overflowed within its floodplain.


The information contained in this product has no field validation.

Source Images

Pre-disaster image:
SENTINEL 2A (2025-06-03)

Post-disaster image:
MUX/CBERS-4A (2025-11-09)

WGS 84



18°34'1"N

18°34'1"N

18°33'29"N

18°33'29"N

18°32'56"N

18°32'56"N

La salle grande place petite
rivière de l'ogâne

La salle grande place petite
rivière de l'ogâne

Momance River

Momance River

Grand Place

Grand Place

Pre-disaster

Post-disaster

72°34'5"W

72°33'36"W

72°34'5"W

72°33'36"W