EARTHQUAKE IN VENEZUELA

Valle de Oro, San Diego

Act-1036/Call-1186





Google Terrain

According to local news reports, houses in the Valle de Oro neighborhood, San Diego, sustained structural damage, including wall cracks and partial roof collapses.

Urbanización Valle de Oro

- Potential structural damage

Image sources

Post-disaster imagery:
CBERS-4A/WPM (2026-07-14)

The information in this product has not been field validated.

WGS 84

0 50 100 m

N

Copyright: Contains modified data of CBERS/AMAZONIA, Copyright INPE 2026.