
EARTHQUAKE IN VENEZUELA

Caraballeda, La Guaira

Act-1036/Call-1186





Google Terrain

Collapsed structures identified from

- Satellite image
- Aerial footage

Image sources

Pre-disaster imagery:
WORLDVIEW (2026-04-05)

Post-disaster imagery:
GLOBAL (2026-06-25)

The information in this product has not been field validated.

WGS 84

N 0 50 100 m

Copyright: ©2026, Maxar, USG Plus
© BlackSky Inc. 2026.